

THURSDAY 25 JUNE 2026

A zipper's stitch line kept showing on the outside



Took part **3**
Where **aikyam space, Fort Kochi**
Run by **Mary Gracy**

Facilitators **1**
Club **Stitching Club**

The stitching team continued working on the new bag design while trying to attach the zipper neatly. We found the stitching line became visible on the outside of the bag, which affected the final look. We spent time discussing different methods and sharing ideas to achieve a cleaner finish without compromising the strength of the bag.

The text of this report is licensed under the Creative Commons Attribution 4.0 International License (CC BY 4.0). To view a copy of the license, visit <https://creativecommons.org/licenses/by/4.0/>. Photographs: all rights reserved.